



Dear Customer,

Thank you for choosing an Artec scanner!

Please read and note the recommended operation conditions carefully before starting to use your new device.

Temperature: from + 15°C to + 35°C

Humidity: non-condensing, up to 80% for temperature (25±10) °C

Exposure to the following factors could lead to a deterioration in the device's performance:

- Condensation
- Direct exposure to any liquid
- Dust

In case you have any questions, please feel free to contact us at support@artec-group.com.

We wish you success and hope you'll enjoy your working experience with Artec 3D scanner.

Your Artec Team



Visit our website
to find out more
www.artec3d.com